

09/25/03

6104420




FIG. 1

20/40




FIG. 2

TO COMMUNICATION LINE




FIG. 3







FIG. 4






FIG. 7




FIG. 8






FIG. 9



• ERROR MADE IN READING OPTICAL SYSTEM

FIG. 10



• ERROR MADE IN LASER OPTICAL SYSTEM

FIG. 11